Mazda North American Operations



TO: All Mazda Dealership General Managers, Service Managers, and Parts Managers

DATE: January 2008 (Original October 2004)

SUBJECT: 2004 MAZDA3 Crash Zone Sensor Recall 2304J

Revised Parts and Warranty Information

Mazda Motor Corporation has decided that a defect, which relates to motor vehicle safety, exists in certain 2004 MAZDA3 vehicles produced from June 24, 2003 through March 22, 2004.

On certain 2004 MAZDA3 vehicles, a crack in the airbag crash zone sensor housing can allow water to enter the sensor, causing a short circuit and illuminating the airbag warning light. If this problem exists, the airbag will not deploy as designed in certain types of frontal crashes, increasing the risk of death or serious injury to the driver and front seat passenger.

Owners of affected vehicles will be notified by first class mail beginning October 28, 2004.

This package contains important information about recall campaign 2304J:

Attachment I Dealer Service and Parts information
Attachment II Inspection and Repair procedures

Attachment III Owner notification letter

Dealer Report

The National Traffic and Motor Vehicle Safety Act prohibits the delivery of any subject vehicles without performing the necessary repair for defects or failures. Failure to perform applicable recalls before sale can result in extensive dealer fines and penalties from the Federal Government. Therefore, you must complete this recall for all affected new vehicles in your inventory prior to delivery.

To help you effectively perform this recall, Mazda has developed the following resources:

- 1. Service and Parts recall instructions follow (Attachment I), were e-mailed to your Service Department, and are also available on the ESI website.
- 2. Inspection and repair procedures follow (Attachment II), are also available on the ESI website.
- 3. We recommend using the enclosed report of registered owners in the dealer's area to encourage customers to come in for the recall (with recall reminder postcards, for example). Dealers may use such owner information for the sole purpose of conducting and performing this safety recall, and for no other purpose. Using it for marketing activities is strictly prohibited and could subject

your dealership to serious fines. The information in this report is protected by state privacy and other applicable laws regarding disclosure of personal and/or confidential, restricted or blocked information. It is the dealer's responsibility to protect the confidentiality of owner records and prevent the release of information to other parties.

In California, privacy laws prevent the release of names and addresses on this report.

- 4. For technical assistance, call the Technical Assistance Hotline at (888) 832-8477.
- 5. For warranty questions, contact the Corporate Dealer Assistance Group at (877) 727-6626.

Please make certain that the appropriate personnel in your dealership are aware of these resources and are familiar with the details of this recall before responding to customer inquiries.

We apologize for any inconvenience this program may cause you and your customers. Please keep in mind that owners of 2001 and newer models are eligible to receive a rental car at no charge. Your understanding and support in carrying out this campaign is greatly appreciated.

Sincerely,

Susumu Niinai Director, Technical Services Mazda North American Operations

CONDITION OF CONCERN

On certain 2004 MAZDA3 vehicles, a crack in the airbag crash zone sensor housing can allow water to enter the sensor, causing a short circuit and illuminating the airbag warning light. If this problem exists, the airbag will not deploy as designed in certain types of frontal crashes, increasing the risk of death or serious injury to the driver and front seat passenger.

SUBJECT VEHICLES

Model	VIN Range	Build Date Range
2004 MAZDA3	JM1BK****41 100088 - 169916	June 24, 2003 through March 22, 2004

Note: The asterisk symbol "*" can be any letter or number.

OWNER NOTIFICATION

Mazda will notify U.S. owners by first class mail beginning October 28, 2004.

PARTS INFORMATION

Original Part Number (BPYK-57-KX0) is obsolete and no longer available from supplier. Dealers ordering the obsolete kit (BPYK-57-KX0) will receive the following parts, which can also be ordered individually:

Description	Part Number	Quantity	
Crash Zone Sensor	BP4K-57-K1XB	1	
Stay, Lock	BP4K-52-15YA	1	
Screw, Tapping	9978-60-635	1	
Campaign Label	9999-95-065A-00	1=sheet of 18	Mstore
		labels	(no charge)

Use MStore to order additional Campaign labels (1=sheet of 18 labels).

WARRANTY CLAIM PROCESSING INFORMATION

Where Kit Part Number **BPYK-57-KX0** is installed (no changes from original)

		Inspection &	Inspection &	
	Inspection only	Crash Zone Sensor	Crash Zone Sensor Replacement &	
	inspection only	Replacement		
			DTC deleting**	
Warranty Type Code	R	R	R	
Symptom Code	99	99	99	
Damage Code	99	99	99	
Process Number	A4459H	A4459H	A4459H	
Part Number	BPYK-57-KX0	BPYK-57-KX0	BPYK-57-KX0	
Main Cause	DFTR-37-NAU	BF 1K-37-KA0	BF 1K-37-KA0	
Quantity	0	1	1	
Labor Operation Code	XX769XR1	XX769XR2	XX769XR3	
Labor Hours	0.2	0.3	0.4	

^{**} Applicable only if vehicle comes into the dealer with the Air Bag Warning Light on.

		Inspection &	Inspection &	
	Inspection only	Crash Zone Sensor	Crash Zone Sensor	
	inspection only	Replacement	Replacement &	
			DTC deleting**	
Warranty Type Code	R	R	R	
Symptom Code	99	99	99	
Damage Code	99	99	99	
Process Number	A4459H	A4459H	A4459H	
Part Number	BPYK-57-KX0	BP4K-57-K1XB	BP4K-57-K1XB	
Main Cause	DFTR-37-NAU	BF4R-57-KTAB	6P4K-57-KTAB	
Quantity	0	1	1	
Labor Operation Code	XX769XR1	XX769XR2	XX769XR3	
Labor Hours	0.2	0.3	0.4	
Related Part No/Qty		BP4K-57-K1XB / 1	BP4K-57-K1XB / 1	
		9978-60-635 / 1	9978-60-635 / 1	

^{**} Applicable only if vehicle comes into the dealer with the Air Bag Warning Light on.

RENTAL CAR

A rental car may be provided to the customer if eligible based on the terms and conditions of the Rental Car Reimbursement Program, policy 12.0. Rental car reimbursements are available only on 2001 and newer vehicles within the mileage and time limitations under the New Vehicle Limited Warranty. If the customer was placed in a rental car while the campaign was being completed and the vehicle is not within the mileage and time limitations, you must obtain authorization for the rental. Submit a separate **claim/problem** using the standard rental claim information.

Warranty Type Code	A
Symptom Code	99
Damage Code	99
Part Number Main Cause	5555-RE-NTAL
Part Quantity	0
Labor Operation Code	MM012XRX
Labor Hours	0.0
Sublet – Rental Car	
Sublet Invoice Number	Number from Rental Invoice or Dealer Purchase Order
Sublet Type Code	Enter "L"
Sublet Amount	Up to \$26.00 per day for the number of days customer had rental car

Rental expenses that exceed the two-day limit will require prior DCSM Authorization, as outlined in the Rental Car Reimbursement Program policy.

VERIFY THE VEHICLE NEEDS THE RECALL

1. Verify the vehicle is within the following ranges:

Model	VIN Range	Build Date Range	
2004 MAZDA3	JM1BK****41 100088 - 169916	June 24, 2003 through March 22, 2004	

If the vehicle is within the above ranges, go to step 2.

If vehicle is not within the above range, return it to inventory or the customer.

2. Perform a Warranty Vehicle Inquiry using your eMDCS System and inspect vehicle for an Authorized Modification Label RECALL 2304J attached to the vehicle's bulkhead.

eMDCS System - Vehicle Status Inquiry Results

If eMDCS displays:	Campaign Label is:	Action to perform:	
		Contact the Mazda Corporate	
RECALL 2304J	Present	Dealer Assistance Group at (877)	
OPEN		727-6626 to update vehicle history	
	Not present	Proceed to "REPAIR PROCEDURE"	
RECALL 2304J CLOSED	Present	Return vehicle to inventory or customer	
	Not present	Complete a label and apply to vehicle's hood or bulkhead	
RECALL 2304J is not displayed	Does not apply	SSP does not apply to this vehicle. Return vehicle to inventory or customer	

Note: Verify the recall number as the vehicle may have multiple labels.

REPAIR PROCEDURES

Please refer to Attachment II.



October 2004

2004 Mazda3 Crash Zone Sensor Recall 2304J

Dear Mazda Owner:

This notice is being sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Mazda Motor Corporation has decided that a defect, which relates to motor vehicle safety, exists in certain 2004 Mazda3 vehicles produced from June 24, 2003 through March 22, 2004. If you are a recipient of this notice, your vehicle is included in this campaign.

What is the problem?

On certain 2004 Mazda3 vehicles, a crack in the airbag crash zone sensor housing can allow water to enter the sensor, causing a short circuit and illuminating the airbag warning light. If this problem exists, the airbag will not deploy as designed in certain types of frontal crashes, increasing the risk of death or serious injury to the driver and front seat passenger.

What will Mazda do?

Your Mazda dealer will inspect the crash zone sensor and replace it, if necessary, with a modified one **free of charge**. The repair should take approximately one hour to complete. However, it may take longer depending on the service workload at your Mazda dealership.

As a reminder, the Mazda Driver's Assurance Plan may provide alternate transportation when your vehicle is at an authorized Mazda dealership for a warranty repair. To be eligible for alternate transportation, your vehicle must be within the mileage and time limitations under the Mazda New Vehicle Limited Warranty and adhere to the Rental Car Reimbursement policy. Ask your dealer for details about the Mazda Rental Car Reimbursement Program.

What should you do?

Mazda is concerned about your safety, and we encourage you to make an appointment with any authorized Mazda dealer to have the crash zone sensor inspected and replaced, if necessary, as soon as possible. You do not need to bring this notice to the dealer, but it may assist in the checkin process.

What if you have already paid for a repair of the crash zone sensor?

If you have already paid for the inspection/repair or replacement of the crash zone sensor due to a defect in the sensor, you may be eligible for reimbursement of reasonable repair expenses based on Mazda's repair standards. Please complete the enclosed "Reimbursement Application Form," including the necessary documentation, and mail it to us in the pre-addressed envelope provided, allowing 6-8 weeks for processing.

Where is the closest Mazda dealer?

To locate your nearest Mazda dealer, visit our web site and try our "Locate a Dealer" feature at www.MazdaUSA.com or consult your local yellow pages.

Moved or no longer own this vehicle?

If you have moved or no longer own your Mazda3, please complete the enclosed prepaid *Information Change Card* as soon as possible. This enables us to update our records and notify the current owner.

Federal law requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.

Still have questions?

Sincerely,

If you have any questions regarding this campaign, please contact our Customer Assistance Center at (800) 222-5500, option #4.

If Mazda or its dealers do not repair the defect free of charge and within a reasonable amount of time, you may notify the Administrator of the National Highway Traffic Safety Administration, 400 Seventh Avenue, SW, Washington, D.C. 20590. You may also call their toll-free Auto Safety Hotline at (888) 327-4236.

Your safety is a priority for Mazda. We actively work to improve our products and search for solutions to improve your ownership experience. Please accept our apologies for any inconvenience this program may have caused you.

Mazda	North	Americ	an O	perati	ions